



STATE OF COLORADO

OIL & GAS CONSERVATION COMMISSION

Oil & Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, Colorado 80203
Phone: (303) 894-2100
FAX: (303) 894-2109

February 14, 1995

1-61



DEPARTMENT OF
NATURAL
RESOURCES

Roy Romer
Governor

Ken Salazar
Executive Director

Richard T. Griebling
Director

Brian J. Macke

Patricia C. Beaver
Technical Secretary

Wendall Wacker
17420 Morgan County Road W
Fort Morgan, Colorado 80701

RE: Request for information regarding historically plugged wells on your property, adjacent to the east boundary of the CIG, Young Gas Storage facility, and seismic truck tracks across your land.

Dear Mr. Wacker:

I have reviewed the below list of plugged wells. Each of the wells were plugged in approval with Oil and Gas Commission. I have discussed the concern you have about bottom hole plugs in these wells with Mr. Greg Gettman of Colorado Interstate Gas Company (CIG), Colorado Springs. He has assured me that CIG is willing to re-enter and replug any well that the Oil and Gas Commission believes will add to the security of the CIG Young facility and public safety near the facility. It is necessary for you to allow access to the sites on your property.

Since this action will be in your interest and the operation at the expense of the CIG, I feel that any damage fees should be waived. The re-entry shall occur using the State of Colorado Oil and Gas Commission Surface bond. The wells in question shall be replugged in compliance and supervision of the Oil and Gas Commission Area Engineer. Restoration of the surface will be in agreement with the Oil and Gas Conservation Commission Rules with restoration to be completed within 3 months after plugging the re-entered well.

The wells I have reviewed include:

#1 Plumb, SW NW 13-4N-58W. Plugs set include 30 sacks at 5760-5680', 10 sacks at 128', 5 sacks at surface.

#1 Hemphill, SW NW 12-4N-58W. Plugs set include 25 sacks at 160-80', 8 sacks at surface.

Since the #1 Best has a bottomhole plug it is unnecessary to re-enter this well. However, the #1 Hemphill will be considered for re-entry with your permission granted in writing to CIG and the State of Colorado Oil and Gas Commission.

It is my understanding that damage payment and release has been granted for the seismic activity. Please contact me at 842-4465 if you have further questions.

Sincerely,



Eddie B. Binkley
Northeast Area Engineer

cc: Dave Dillon, OGCC
Greg Gettman, CIG