

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2019

Submitted Date:

07/02/2019

Document Number:

689900948

FIELD INSPECTION FORM

Loc ID 307317 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	
		roboss@tcenergyllc.com	
		ediefitzgerald@tcenergy.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217446	WELL	PR	10/01/1996	GW	071-06223	APACHE CANYON 20-1	RI

General Comment:

This is a Stormwater inspection.
This is a follow up to the previous inspection #689900773.
Corrective actions of the previous inspection have not been performed.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [The main road in The Southfork has areas of road damage \(potholes\) causing vehicles to widen the road. The road needs to be graded and maintained. There is erosion occurring off the northeast side of the pad. Sediment is accumulating near the culvert of the access road. The corrective action of the previous inspection has not been performed. Previous corrective action date remains for possible enforcement. Corrective action needs to be performed immediately. See Attached Photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 07/01/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900949	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867586