

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402058010

Date Received:

05/29/2019

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

Labowskie, Steve

steve.labowskie@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 687904741

Inspection Date: 05/15/2019

FIR Submit Date: 05/10/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 326067

Location Name: MW JOHNSON G A-M34N8W Number: 16NWNW County: LA PLATA

Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M

Latitude: 37.195509 Longitude: -107.727750

### FACILITY - API Number: 05-067- -00 Facility ID: 215812

Facility Name: MW JOHNSON A Number: 1

Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M

Latitude: 37.195509 Longitude: -107.727750

### CORRECTIVE ACTIONS:

1 ☒ CA# 125042

Corrective Action: Completely clean up impacted material and resolve mechanical/operational issue leading to mixing of oil and waste and precipitation as observed.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 05/28/2019

Due to vibration the flex hose appeared to have reoccurring puncture. A stand to elevate the muffler and hose off

Operator Comment: of the ground was built and installed to eliminate the risk of reoccurrence of puncture of flex hose. new hoses have been installed on both the inlet and outlet of the muffler. The outlet has been secured through the screen to prevent it from staining edge of outside of box. Impacted soils have been removed and containment boxes emptied of stormwater. Please see attached.

COGCC Decision: Approved

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions addressed see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed:

Title: Compliance Specialist

Date: 5/29/2019 12:42:10 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402058010	FIR RESOLUTION SUBMITTED
402058025	CA completion document

Total Attach: 2 Files