

**Inspection Photos**  
**Operator: SG Interests**  
**Location/API #: 051-06059**  
**Date: 6-19-2019**



Photo 1. View of the northeastern cut-slope from the well pad entrance facing northward. Erosional blankets are torn and need repair or replacement.





Photo 2. View of rilling within the northern cut-slope.





Photo 3. View of the southern project area from the southeastern corner facing westward.