

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402062104

Date Received:

07/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 1050 17TH STREET SUITE 2500
City: DENVER State: CO Zip: 80265

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Pohl, April</u>	<u>505-444-0520</u>	<u>apohl@enduringresources.com</u>
<u>Felix, Andrea</u>		<u>afelix@enduringresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900237
Inspection Date: 04/22/2019 FIR Submit Date: 04/30/2019 FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC Company Number: 10663
Address: 1050 17TH STREET SUITE 2500
City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 326208

Location Name: INDIAN CREEK WHEELER-M34N10W Number: 13SENW County: LA PLATA
Qtrqtr: SENW Sec: 13 Twp: 34N Range: 10W Meridian: M
Latitude: 37.193352 Longitude: -107.885371

FACILITY - API Number: 05-067-00 Facility ID: 216044

Facility Name: INDIAN CREEK WHEELER Number: 13-2
Qtrqtr: SENW Sec: 13 Twp: 34N Range: 10W Meridian: M
Latitude: 37.193352 Longitude: -107.885371

CORRECTIVE ACTIIONS:

1 CA# 124768

Corrective Action: Revegetate the well pad cut-slopes. Stabilization measures need to be installed until slopes are revegetated (also described below). Date: 05/31/2019

Response: CA COMPLETED Date of Completion: 07/01/2019

Operator Comment: Hydroseeding completed

COGCC Decision: _____

COGCC
Representative:

2 CA# 124769

Corrective Action: Stormwater controls in the southeastern project area need maintenance and replacement as needed. Stormwater controls are also needed along the access road to stabilize both sides of the culvert and flows entering the stream. Erosion controls are needed on well pad cut-slopes to provide stabilization until they can be stabilized within vegetation. Stormwater and erosion controls need to be selected and installed using good engineering practices such as those described in CDOT manuals.

Date: 05/31/2019

Response: CA COMPLETED

Date of Completion: 05/28/2019

Operator
Comment:

Stormwater controls corrective actions completed

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: APRILE POHL

Signed: _____

Title: REGULATORY SPECIALIST

Date: 7/8/2019 8:32:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402098131	Rock work completed
402098133	Hydroseeding completed

Total Attach: 2 Files