

Inspection Photos
Location Name: DeChant –State #2
Location ID: 317781



Photo 1 WH and WH sign. Sign needs to be replaced due to having bullet holes. At time of inspection WH appears to be leaking by top of casing.