

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402072012

Date Received:

06/13/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Roy, Catherine</u>		<u>catherine.roy@state.co.us</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandi</u>	<u>505-324-5122</u>	<u>mray@hilcorp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800491

Inspection Date: 03/26/2019

FIR Submit Date: 04/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 312037

Location Name: SCHUYLER 34-9-M34N9W Number: 30NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 30 Twp: 34N Range: 9W Meridian: M

Latitude: 37.158530 Longitude: -107.865030

FACILITY - API Number: 05-067-00 Facility ID: 216505

Facility Name: SCHUYLER 34-9 Number: 30-2

Qtrqtr: NWSE Sec: 30 Twp: 34N Range: 9W Meridian: M

Latitude: 37.158530 Longitude: -107.865030

CORRECTIVE ACTIONS:

1 ☒ CA# 123773

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.

Date: 05/02/2019

Response: CA COMPLETED

Date of Completion: 04/03/2019

The leaking stuffing box has been repaired, and all free standing fluids were removed via hydro-vac.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 123774

Corrective Action: Control and clean up spills/releases and clean up per Rule 906.a. Contct COGCC EPS staff.

Date: 04/03/2019

Response: CA COMPLETED

Date of Completion: 04/03/2019

Operator
Comment:

The leaking stuffing box has been repaired, and all free standing fluids were removed via hydro-vac.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 123775

Corrective Action: The operator shall ensure compliance with Rule 907.a.1.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 06/12/2019

Operator
Comment:

Coal fines removed from location

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: _____

Title: Operation/Regulatory TECh

Date: 6/13/2019 12:25:07 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402072012	FIR RESOLUTION SUBMITTED
402074144	Coalfines
402074145	Cleaned Area
402074146	Cleaned Area 3
402074148	Cleaned Aera 2

Total Attach: 5 Files