

**FORM  
INSP**Rev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

685101328**FIELD INSPECTION FORM**

Loc ID 317973 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240288	WELL	PR	07/07/1997	GW	123-08076	HOPKINS 41C-19 2	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	no capacity label on water tank/illegible		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/22/2019

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue: piping in separator appears to be leaking on ground.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 06/22/2019
Type	TRASH		
Comment:	blue bucket by pumpjack		
Corrective Action:	Comply with rule 603 f		Date: 06/05/2019
Type	OTHER		
Comment:	Stained soil inside separator house / outside of separator house		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e		Date: 06/22/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric box		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
--------	-----	--	--

Comment:	Pilot appears not to be lit on heater on separator.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/23/2019

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 240288	Type: WELL	API Number: 123-08076	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Fail	

Comment: Storage of chemicals and material

Corrective Action: Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2) B

Date: 06/05/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 7/15/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resouces Inc.- API 123-08076 -Hopkins 41C-19 2 Weld County Colorado.</p> <p>While there, I observed Producing Well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Follow up inspection for Document # 693500136</p> <p>Corrective Actions from previous inspection are delinquent.</p> <p>no capacity label on water tank/illegible</p> <p>Install sign to comply with Rule 210.d. 6/22/19</p> <p>Mechanical issue: piping in separator appears to be leaking on ground.</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/22/19</p> <p>Stained soil inside seperator house / outside of separator house</p> <p>Properly treat or dispose of oily waste in accordance with 907.e 6/22/19</p> <p>blue bucket by pumpjack</p> <p>Comply with rule 603 f 6/5/19</p> <p>Pilot appears not to be lit on heater on separator.</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.5/23/19</p> <p>Storage of chemicals and material</p> <p>Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2) B 6/5/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/15/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402111252	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880325">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880325</a>
685101329	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880296">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880296</a>