

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

695101120**FIELD INSPECTION FORM**

Loc ID 308880 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284264	WELL	PR	07/12/2007	GW	071-08761	BIG TIMER 32-19	PR

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	IMMEDIATELY STOP PRODUCING WELL ON A VACUUM. DO NOT OPERATOR VACUUM EQUIPMENT (COMPRESSOR) WITHOUT COMPLETE COMPLIANCE WITH RULE 331 AND 802.		Date: 07/24/2019

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 284264 Type: WELL API Number: 071-08761 Status: PR Insp. Status: PR

Complaint

Comment: STEVE LABOWSKIE PERFORMED A SOUND STUDY STARTING @ APPROXIMATELY 08:45 A.M. FOR 15 MINUTES. WIND SPEED APP. 1-2 MPH. TEMP 63*
SOUND METER SET @ 100' FROM COMPRESSOR EXHAUST. results are 54.4 AVERAGE db (a) calc. to 43.5 db (a) @ 350'.

STEVE LABOWSKIE PERFORMED A SOUND STUDY at complaintants residence 17775 county road 51.0 STARTING @ APPROXIMATELY 10:00 A.M. FOR 15 MINUTES. WIND SPEED APP. 1-2 MPH. TEMP 65*
SOUND METER SET @ 25' FROM residence.

Corrective Action: TURN EXHAUST OUTLET ON ENGINE SKID FOR DRIVEHEAD 180* SO IT IS NOT POINTING IN THE DIRECTION OF THE HOME TO THE NORTHWEST OF LOCATION
COMPLY WITH RULE 802

Date: 07/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101121	SOUND SURVEY AT LOCATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889777
695101122	SOUND SURVEY AT RESIDENCE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889778