

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2019

Submitted Date:

07/18/2019

Document Number:

679704780**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 314479 Moran, Rick 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON USA INCCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
 2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck		chuck.browning@state.co.us	
Sanford, Anita		atlx@chevron.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228812	WELL	IJ	12/18/2017	ERIW	103-05798	MCLAUGHLIN, A C 12	IJ

General Comment:

COGCC Inspection Report Summary.

On 7-18-2019 at approximately 11:45, inspector Rick Moran, conducted a follow up inspection at Chevron well AC McLaughlin 12 in Rio Blanco county of FIR document 693800261.

The following compliance issues were identified as resolved:

- 1) Well head sign.

Additional compliance issues were identified:

- 1) "911" missing on well head sign. Photo 2. Complete by 8-18-2019.
 2) Hole in location berm. Photo 3. Complete by 8-18-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704780.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Missing "911" on sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/19/2019

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 228812 Type: WELL API Number: 103-05798 Status: IJ Insp. Status: IJ**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>WEBR</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>03/09/2018</u>
			AnnMTReq: _____

Comment: Injection well.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: [Break in location berm at lowest elevation of slopping location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 08/19/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402114924	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884029
679704781	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884019