

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

695101112**FIELD INSPECTION FORM**

Loc ID 307708 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89246	WELL	PR	11/05/1999	GW	071-06826	WORM 33-36	PR

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	PHOTO 3 TROUGH 8: ACTIVE ONGOING RELEASE AT WELLHEAD APPEARSE TO BE GREATER 1 BBL PRODUCED WATER. NO CONTAINMENT. OPERATOR ARIVED ON LOCATION WHILE I WAS STILL PERFORMING MY INSPECTION AND SHUT EQUIPMENT DOWN AND REPAIRED LEAK. OPERATOR ALSO CALLED A DRIP TRUCK TO COME IN AND REMOVE STANDING PRODUCED WATER FROM LOCATION. I PASSED DRIP TRUCK JUST OFF LOCATION AS I WAS LEAVING.			
Corrective Action:	IMEDEATELY CONTROL RELEASE, RESPOND TO SPILL AND CONTACT COGCC EPS STAFF AND FILE SPILE REPORT AS REQUIRED BY RULE 906.			Date: <u>07/24/2019</u>

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	APPEARED THAT POLISH ROD PACKING WAS LEAKING.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>07/24/2019</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 89246 Type: WELL API Number: 071-06826 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402120438	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889124">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889124</a>
695101113	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889118</a>