



Federal 12-89-7 #1 —API—051-06110

Inspection Doc 693900449 -6/18/19

CA #1 of 1—Stabilize erosion and install SW controls /Monitor cracks in berm.