

Inspection Photos

08/02/2019

Operator: WHITING OIL & GAS CORPORATION
- 96155

Location ID: 435945
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435945



Photo 1: Photo taken from the north end of the location, facing east. Photos 1-4 provide an overview of the location and reclamation from east, southeast, southwest to west.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435945



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435945



Photo 5: Photo taken from the northwestern end of the location, facing south. Photo shows additional reclamation activities appear to have recently been conducted on areas of the location.



Photo 6: Photo taken from the west end of the location, facing south. Photo shows areas of the northern access road that may require additional reclamation.

Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435945



Photo 7: Photo taken from the west end of the location, facing west. Photo also shows culvert remaining at road.



Photo 8: Photo taken from the access road, facing east. Photo shows a second culvert remaining on road.

Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435945



Photo 9: Photo taken from the southwest corner of the location. Photo shows additional road disturbance on the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: WHITING OIL & GAS CORPORATION - 96155
Location ID: 435945



Photo 10: 2017 COGCC COGIS aerial imagery. Dotted lines (yellow) show access road/extra road disturbance that require reclamation. Solid line in orange show area of access road were additional reclamation may be required (see photo 6).

