

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402147581

Date Received:

08/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mack, Ronald

ronaldmack@tcenergyllc.com

ediefitzgerald@tcenergyllc.com

robfoos@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901011

Inspection Date: 07/15/2019

FIR Submit Date: 07/17/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308377

Location Name: APACHE CANYON-634S68W Number: 1SESE County: LAS ANIMAS

Qtrqr: SESE Sec: 1 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.108970 Longitude: -104.941180

FACILITY - API Number: 05-071- -00 Facility ID: 270570

Facility Name: APACHE CANYON Number: 1-16

Qtrqr: SESE Sec: 1 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.108970 Longitude: -104.941180

CORRECTIVE ACTIONS:

1 CA# 128213

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 07/19/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

The well head packings were tightened to stop the water leak.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 128214

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/16/2019

Response: CA COMPLETED

Date of Completion: 08/12/2019

Operator
Comment:

The tire ruts on the access road were corrected.

COGCC Decision:

COGCC
Representative:

3 CA# 128215

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/16/2019

Response: CA COMPLETED

Date of Completion: 08/14/2019

Operator
Comment:

The fluid accumulation was removed from the liquid ring skid. The impacted soil was removed from location and all fittings were securely fastened.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: SR. Environmental Tech.

Date: 8/16/2019 2:26:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files