

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2019

Submitted Date:

08/26/2019

Document Number:

693501177

FIELD INSPECTION FORM

Loc ID 317831 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections
Gomez, Jason		jason.gomez@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Medina, Justin		justin.medina@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240034	WELL	PR	06/01/2018	OW	123-07822	NESSU 15	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well head sign reflects old operator on sign		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 07/24/2019
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Barb wire		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:	Date:
--------------------	-------

--

Inspected Facilities

Facility ID: 240034 Type: WELL API Number: 123-07822 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday August 26 2019 at approximately 2:59 PM, I, Inspector Randy Silver, conducted an on-site inspection at a KP Kauffman site Nessu #15, at API# 05-123-07822 in Weld County Colorado. While there, I observed Production well site. During this inspection the following possible compliance issues were observed: Well head sign: Rule 210 e Correction date of 7-24-19 See photo #2 This is follow up inspection to Doc#693500491 and new complaint. At time of inspection it appears stained soil has been addressed, well was not running at time of inspection so I could not see if saddle bearing had been addressed. Pumping jack is not able to operate due to PU belts appear to be torn off and laying on ground. New well head sign had not been installed at time of inspection, old operator still on original sign. I spoke with complainant/landowners, Brittney White and Julie Hladky who stated gates to the entrance to the well site had been left open and their horses got out into open pasture. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402156282	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4919962
693501178	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4919936