

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2019

Submitted Date:

09/03/2019

Document Number:

690900074

**FIELD INSPECTION FORM**

Loc ID 414031 Inspector Name: FISCHER, ALEX On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10619  
Name of Operator: INSPIRE OIL & GAS INC  
Address: 1400 BROADFIELD BLVD SUITE 600  
City: HOUSTON State: TX Zip: 77084

**Findings:**

- 10 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	
Ritz, Bo	713-269-4969	britz@inspireoilandgas.com	
Neidel, Kris		kris.neidel@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412127	WELL	PR	10/20/2012	GW	057-06490	Silver Spur Minerals 35-2H	EI

**General Comment:**

On August 21, 2019 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Inspire Oil and Gas Inc's Silver Spur Minerals 35-2H, API 05-057-06490. Weather was sunny and temperature 67 degree F. For the most recent field inspection report of this facility, please refer to document #689800259. Note: The corrective action (CA) dates of document #689800259 still remain.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019
Type	OTHER		
Comment:	Sign not posted or information inaccurate at entrance off of Hwy 14.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Note: Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	10/03/2019

<b>Emergency Contact Number:</b>			
Comment:	Location sign off of Hwy 14. (Note: phone number was not active on 9/3/2019). Well sign. (Note: phone number was not active on 9/3/2019). Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.d. Install sign to comply with Rule 210.e.	Date:	10/04/2019

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Tubing and misc equipment stored on Location.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/13/2017

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Condensate	Tank	<= 1 bbl	
Comment:	Tank 0030, staining beneath hammer unions.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 09/04/2019

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		Inadequate
Comment: <b>Berm is not consolidated.</b>				
Corrective Action: <b>Repair or install berms or other scndary containment devices per Ruls 605.a.(4).</b>				Date: <b>10/13/2017</b>

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		Inadequate
Comment: <b>Berm is not consolidated.</b>				
Corrective Action: <b>Repair or install berms or other scndary containment devices per Ruls 605.a.(4).</b>				Date: <b>10/13/2017</b>

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 412127 Type: WELL API Number: 057-06490 Status: PR Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<b>Note:</b> The corrective action (CA) dates of document #689800259 still remain. The operator shall immediately address the drips from the leaking hammer unions.	fischera	09/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900075	INSP Photo Silver Spur Min 0505706490 20190821ajf	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927074</a>