

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402166357

Date Received:  
09/11/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON USA INC

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Chris Patterson</u>	<u>970-675-3814</u>	<u>spwu@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690900072

Inspection Date: 08/22/2019

FIR Submit Date: 09/03/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON USA INC

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqr: NENW Sec: 35 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.191414 Longitude: -107.907919

FACILITY - API Number: 05-103-00 Facility ID: 149002

Facility Name: WILSON CREEK LANDFARM Number: \_\_\_\_\_

Qtrqr: NENW Sec: 35 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.191414 Longitude: -107.907919

CORRECTIVE ACTIONS:

**1** CA# 129951

Corrective Action: Appropriate measures shall also be implemented to prevent access to the centralized facility by wildlife or domestic animals.

Date: 10/03/2019

Response: CA COMPLETED

Date of Completion: 09/02/2019

Operator Comment: Fence and wire was repaired.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 129952

Corrective Action: Remove trash and debris (liner and metal pieces) during tilling operations and properly dispose.

Date: 09/13/2019

Response: CA COMPLETED

Date of Completion: 09/02/2019

Operator  
Comment:

Trash and debris was removed.

COGCC Decision:

COGCC  
Representative:

**3** CA# 129953

Corrective Action: Remove free standing fluids and hydrocarbons. (Note: Chevron personnel and Stantec were notified on location to address the free standing fluids and potential hydrocarbons.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 08/26/2019

Operator  
Comment:

Chevron stabilized the free liquids using stockpiled material from cell 2 for soil shredding activities. The stabilized material was then stockpiled near the entry to Cell 1 and moved to the unlined area (as a stable material no free liquids) and windrowed for treatment using soil shredding technology.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corective Actions for FIR report addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: \_\_\_\_\_

Title: HES Specialist

Date: 9/11/2019 2:47:51 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402166359	CA#129953_Landfarm Cell 1_stabilization
402166361	CA#129953_Landfarm Cell1_stabilization#2
402173444	CA#129951 Fence repaired
402173445	CA#129951 Fence repaired
402173450	CA#129952 Debris Removed

Total Attach: 5 Files