

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2019

Submitted Date:

09/07/2019

Document Number:

689803113**FIELD INSPECTION FORM**Loc ID 466705 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10728Name of Operator: GULF EXPLORATION LLCAddress: 9701 N BROADWAY EXTENSIONCity: OKLAHOMA CITY State: OK Zip: 73114**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Strickland, Sean		sstrickland@gulfexploration.com	
Ash, Margaret		margaret.ash@state.co.us	
Colby, Lou		lou.colby@state.co.us	

General Comment:**COGCC Inspection Report 689803113 Summary**

On Friday 9/6/2019 at approximately 13:15, I, Inspector Emily Waldron, conducted a field inspection at Gulf Exploration LLC Eagle Hill 1-32, at 05-057-06625 in Jackson County Colorado.

While there, I observed beginning of move in and rig up activities. 2 housing trailers were on site and contractors were setting them up. No other equipment yet on location.

During this inspection the following possible compliance issues were observed:

No signs on location. No emergency contact on location. Install sign to comply with Rule 210 immediately.

No stormwater controls observed on location or access road. Access road and location are both very dusty, no dust mitigation measures observed. See photos 1-12. Install or repair required BMPs per Rule 1002.f immediately.

I spoke with John Symmons, contractor for Gulf Exploration, on location and explained that appropriate stormwater controls need to be installed immediately on location before move in and rig up commenced. I relayed the same message to Sean Strickland of Gulf Exploration via phone.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report 689803113.

LocationOverall Good: ☐**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	No signs on location.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	09/06/2019

Emergency Contact Number:

Comment: No emergency contact on location.

Corrective Action: Install sign to comply with Rule 210. Date: 09/06/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater controls observed on location or access road. Access road and location are both very dusty, no dust mitigation measures observed. Inspector spoke with John Symmons, contractor for Gulf Exploration, on location and explained that appropriate stormwater controls need to be installed immediately on location before move in and rig up commenced. Inspector relayed same message to Sean Strickland of Gulf Exploration via phone.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/19/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402169151	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931055
689803114	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931054