

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402179780

Date Received:
09/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Susana Lara-Mesa

303-825-4822

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693500947

Inspection Date: 08/05/2019

FIR Submit Date: 08/05/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318470

Location Name: COSSLETT B-61N68W Number: 2SENW County: WELD

Qtrqr: SENW Sec: 2 Twp: 1N Range: 68W Meridian: 6

Latitude: 40.082130 Longitude: -104.972810

FACILITY - API Number: 05-123-00 Facility ID: 241354

Facility Name: COSSLETT B Number: 2

Qtrqr: SENW Sec: 2 Twp: 1N Range: 68W Meridian: 6

Latitude: 40.082130 Longitude: -104.972810

CORRECTIVE ACTIONS:

1 CA# 128932

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator Comment: Mechanical issues: Pumpjack gear box leaking has been fixed.

COGCC Decision: _____

COGCC
Representative:

2 CA# 128933

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Stained soil around Pumping Unit base has been removed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

3 CA# 128934

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/06/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Mechanical issue: Tubing flow lines leaking has been fixed.

COGCC Decision:

COGCC
Representative:

4 CA# 128935

Corrective Action: Install sign to comply with Rule 210.e.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Sign has been updated. Please see attached picture.

COGCC Decision:

COGCC
Representative:

5 CA# 128936

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 09/05/2019

Response: CA COMPLETED

Date of Completion: 09/17/2019

Operator
Comment:

Stained soil around wellhead has been removed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Steve Hamilton

Signed: _____

Title: Field Supervisor

Date: 9/19/2019 3:48:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402179800	Sign updated PIC1
402179801	Stained soil removed PIC2
402179802	Stained soil removed PIC3
402179804	Stained soil removed PIC4

Total Attach: 4 Files