

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2019

Submitted Date:

09/20/2019

Document Number:

694500134**FIELD INSPECTION FORM**
 Loc ID 466705 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10728Name of Operator: GULF EXPLORATION LLCAddress: 9701 N BROADWAY EXTENSIONCity: OKLAHOMA CITY State: OK Zip: 73114**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sean Strickland		sstrickland@gulfoexploration.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466706	WELL	DG	09/07/2019		057-06625	Eagle Hill 1-32	EI

General Comment:

Operator should ensure actions required from previous inspections are completed, this inspection address specific Environmental items documented here and does not necessary address previous required action required.

On 9/12/2019 COGCC staff, Kris Neidel inspected well 057-06625. Weather was 50 degrees and cloudy. COGCC meet with Gulf Exploration employees Sean Strickland and Jordan Williams. The cuttings management area was observed; there was a approximately 70 foot by 30 foot area that had plastic liner placed on the ground, loose soil was placed around the liner to hold it down, moisture content of stored cuttings was low. Details on how Gulf Exploration will manage cuttings was discussed; Gulf Exploration will segment cuttings from the different geological zones and sample each for full COGCC table 910-1. The cuttings were permitted to be buried on location. It was discussed that NO cuttings be buried until demonstration that all cuttings concentrations are below COGCC table 910-1 has been reviewed and approved by COGCC.

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Adequate		
Comment	Drill cuttings are being stored until compliance with COGCC table 910-1 is met.			
Corrective Action	Continue to keep cuttings isolation in the storage area and moisture content to de minimums.			Date: 09/12/2019

Spill/Remediation:

Comment:	
Corrective Action:	Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402184362	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4943198
694500135	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4943195