

Forward to Debbie Baldwin - hydrologist
Debbie
Please investigate & advise
COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION FORM



| | | | |
|--|--------------------------|--------------------------------------|----------------|
| <input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 | |
| <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | Denver, CO 80203 | |
| API No. 05- 075 - <i>legion</i> | | LEASE NAME: <i>N/A Fite! Redeman</i> | |
| LOCATION: <i>C/NW/6 34-9N-53</i> | | OPERATOR: <i>N/A Please NWSE 34</i> | |
| DATE: <i>2-21-95 (9-11 AM)</i> | | INSPECTOR: ED BINKLEY (303) 842-4465 | |
| Insp. Type: <i>CO</i> | Insp. Status: <i>N/A</i> | PA: Y N | Pass/Fail: P F |
| | | Viol.: Y N | NOV: Y N |

| INSPECTION ITEM (RULE) | COMMENTS | INPUT |
|--------------------------------|--|-------|
| Well ID Signs (210) | This appears to be | |
| Pits (Reserve/Production)(904) | a perennial watershed | |
| Fences (604 C.(3), 1003 A.) | spring that travels from | |
| Tank Battery Equipment(604) | NE NW 34 south into | |
| Fire Walls/Berms/Dikes(604) | SWSW 34 stopping (?) | |
| General Housekeeping (603G) | at the sterling Canal. | |
| Spills(Oil/Water)(902,908,911) | There is alkali in | |
| Bradenhead | the SWSW 34-9N-53. | |
| Drilling /Workover (315) | However, vegetation, moss, | |
| Surface Rehabilitation (317) | trees, cat tails are evidenced | |
| Miscellaneous | along the drainage - <i>EF</i> nearest well is NWSE <i>EF</i> | |

| |
|--|
| CORRECTIVE ACTION REQUIRED: <i>Nearest well 34-9N-53</i> <i>Please / Redeman #1</i> <i>API # 075-06228</i> |
| Date Corrective Action Required By: _____ |
| Date Remedied: _____ |

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

Rich Jackson 522 0672 - complained that saltwater is leaking into the watershed causing flooding and loss of surface in this area. Problem began in 1986.

**COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION FORM**

| | | | |
|--|-------------------------|---|--|
| <input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100 | |
| API No. 05- <u>075- 9134</u> | | LEASE NAME: <u>Whittier-Strata</u> ²⁷⁻¹⁰ | |
| LOCATION: <u>NWSE 27-9N-53</u> | | OPERATOR: <u>Strata</u> | |
| DATE: <u>2-21-95</u> | | INSPECTOR: ED BINKLEY (303) 842-4465 | |
| Insp. Type: <u>SR</u> <u>CO</u> | Insp. Status: <u>DA</u> | PA: <u>Y</u> <u>N</u> | Pass/Fail: <u>P</u> <u>F</u> Viol.: <u>Y</u> <u>N</u> NOV: <u>Y</u> <u>N</u> |

| INSPECTION ITEM (RULE) | COMMENTS | INPUT |
|--------------------------------|----------|-------|
| Well ID Signs (210) | | |
| Pits (Reserve/Production)(904) | | |
| Fences (604 C.(3), 1003 A.) | | |
| Tank Battery Equipment(604) | | |
| Fire Walls/Berms/Dikes(604) | | |
| General Housekeeping (603G) | | |
| Spills(Oil/Water)(902,908,911) | | |
| Bradenhead | | |
| Drilling /Workover (315) | | |
| Surface Rehabilitation (317) | | |
| Miscellaneous | | |



(Wheat Field)

Cultivated. No leaks found.

Rick Tadeson - Tenant believes this well is leaking subsurface -

CORRECTIVE ACTION REQUIRED:

There is no indication of leak at the surface within 1/4 mile of this site. EBB

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

Referred to Debbie Baldwin - NW 34-9N-53 Stream is source of complaint about the above well.

White - File Green - Operator Canary - Well Site

COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION FORM

| | | | |
|---|--------------------------------------|---|---|
| <input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100 | |
| API No. 05- 075 - 6228 | LEASE NAME: Rodeman | | |
| LOCATION: NWSE 34-9N-53 | OPERATOR: Lease | | |
| DATE: 2-21-95 | INSPECTOR: ED BINKLEY (303) 842-4465 | | |
| Insp. Type: PR | Insp. Status: PR | PA: Y N | Pass/Fail: P F Viol: Y N NOV: Y N |

| INSPECTION ITEM (RULE) | COMMENTS | INPUT |
|--------------------------------|---|-------|
| Well ID Signs (210) | need name update | |
| Pits (Reserve/Production)(904) | +80 ² (no apparent skin vessel) | |
| Fences (604 C.(3), 1003 A.) | None | |
| Tank Battery Equipment(604) | 2-300, FWKO, VHT | |
| Fire Walls/Berms/Dikes(604) | None | |
| General Housekeeping (603G) | | |
| Spills(Oil/Water)(902,908,911) | oil around pump oil inside pit berm | |
| Bradenhead | | |
| Drilling /Workover (315) | | |
| Surface Rehabilitation (317) | | |
| Miscellaneous | Since 1986 - Landowner - Rick Jackson 522-0672 alleges salt water is leaking into ground water - Referred to Debbie Baldwin - OGCC hydrologist. | |

CORRECTIVE ACTION REQUIRED: 1) Install sign update, tank berms and remediate or remove oily soils.
 2) Verify that pit is not leaking to ground water.

Date Corrective Action Required By: 2/3-14-95
 Date Remedied: 2/4-15-95

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

The landowner referred to PUA well @ NWSE 27-9N-53W when calling in complaint. See file - Steve PTH - 1986 field visit. Mr. Jackson will provide backhoe for hydrologist if needed.