

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402198725

Date Received:
10/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Michael Cugnetti

7208456901

mcugnetti@verdadoil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500472

Inspection Date: 08/14/2019

FIR Submit Date: 08/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

LOCATION - Location ID: 441092

Location Name: Rowe Number: 01N-65W-26 County: _____

Qtrqr: NENW Sec: 26 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.029025 Longitude: -104.632485

FACILITY - API Number: 05-123-00 Facility ID: 441092

Facility Name: Rowe Number: 01N-65W-26

Qtrqr: NENW Sec: 26 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.029025 Longitude: -104.632485

CORRECTIVE ACTIONS:

1 ☒ CA# 129424

Corrective Action: Comply with Rule 1003.e.(1). Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 08/14/2019

Response: CA COMPLETED

Date of Completion: 08/23/2019

Operator
Comment:

Weeds were mowed and grubbed from cut slope. Slope was seeded to try to mitigate weeds over time.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.		
2	<input checked="" type="checkbox"/> CA# 129425		
Corrective Action:	Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.		Date: <u>08/14/2019</u>
Response:	CA COMPLETED		Date of Completion: <u>09/13/2019</u>
Operator Comment:	Slope contour was improved and roughened, waddles were added, and cut slope was seeded.		
COGCC Decision:	Approved pending re-inspection		
COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.		

OPERATOR COMMENT AND SUBMITTAL	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Michael Cugnetti</u>	Signed: _____
Title: <u>EH&S Manager</u>	Date: <u>10/3/2019 2:26:11 PM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402198725	FIR RESOLUTION SUBMITTED
402198803	photo of CA

Total Attach: 2 Files