

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402205726

Date Received:  
10/10/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96155  
Name of Operator: WHITING OIL & GAS CORPORATION  
Address: 1700 BROADWAY STE 2300  
City: DENVER State: CO Zip: 80290

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kyle Waggoner</u>	<u>4326616647</u>	<u>kyle.waggoner@whiting.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200540  
Inspection Date: 08/02/2019 FIR Submit Date: 08/06/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION Company Number: 96155  
Address: 1700 BROADWAY STE 2300  
City: DENVER State: CO Zip: 80290

LOCATION - Location ID: 430127

Location Name: Razor Number: 11H Pad County: \_\_\_\_\_  
Qtrqr: SENE Sec: 11 Twp: 10N Range: 58W Meridian: 6  
Latitude: 40.854544 Longitude: -103.825431

FACILITY - API Number: 05-123-00 Facility ID: 430127

Facility Name: Razor Number: 11H Pad  
Qtrqr: SENE Sec: 11 Twp: 10N Range: 58W Meridian: 6  
Latitude: 40.854544 Longitude: -103.825431

CORRECTIVE ACTIONS:

1 CA# 128970

Corrective Action: Comply with 603.f and conduct weed management. Date: 08/23/2019

Response: CA COMPLETED Date of Completion: 08/15/2019

Operator Comment: The Canadian Thistle was physically removed, bagged, and disposed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 128971

Corrective Action: Conduct stabilization activities on pad per 1003.b. Reclaim the stormwater ditch, and associated stormwater BMPs located on the perimeter of the initial disturbance area and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 09/16/2019

Operator Comment: The perimeter ditch and associated BMP's have been removed and/or reclaimed, seeded, and mulched.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 128972

Corrective Action: Install stormwater BMPs to 1) mitigate ponding within the pad/production areas, 2) prevent potential industrial pollutant contact and 3) to allow for sediment laden-free stormwater discharge from the location

Date: 08/23/2019

Response: CA COMPLETED

Date of Completion: 08/23/2019

Operator Comment: A ditch and berm have been installed leading to a sediment trap surrounding the working surface of the pad.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kyle Waggoner Signed: \_\_\_\_\_

Title: Field Regulatory Manager Date: 10/10/2019 1:16:34 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files