

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402213784

Date Received:  
10/17/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661  
Name of Operator: BISON OIL & GAS II LLC  
Address: 518 17TH STREET #1800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ariana Solis</u>	<u>720-644-6997</u>	<u>asolis@bisonog.com</u>
<u>Abigail Wenk</u>	<u>720-644-6997</u>	<u>awenk@bisonog.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200786  
Inspection Date: 09/20/2019 FIR Submit Date: 09/23/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC Company Number: 10661  
Address: 518 17TH STREET #1800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452871

Location Name: Castor 8-59 Number: 19 County: \_\_\_\_\_  
Qtrqtr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6  
Latitude: 40.644946 Longitude: -104.011983

FACILITY - API Number: 05-123-00 Facility ID: 452871

Facility Name: Castor 8-59 Number: 19  
Qtrqtr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6  
Latitude: 40.644946 Longitude: -104.011983

CORRECTIVE ACTION:

1 CA# 130940

Corrective Action: Install/Repair Stormwater and erosion control BMPs in accordance with 1002.f. Ensure BMPs are installed in accordance with good engineering practice and maintained in proper functioning condition.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 10/07/2019

Operator Comment: Sediment traps have been repaired at the NE & NW corners with a riprap spillway & geotextile lining installed at the inlets.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 130941

Corrective Action: Install/Repair Stormwater and erosion control BMPs in accordance with 1002.f. Ensure BMPs are installed in accordance with good engineering practice and maintained in proper functioning condition.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 10/16/2019

Operator Comment: Bare areas on SE corner of pad have been hydromulched.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 10/17/2019 4:49:41 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402213810	SE Corner
402213813	Sediment Trap

Total Attach: 2 Files