

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402214823

Date Received:

10/18/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abigail Wenk

7206446997

awenk@bisonog.com

Ariana Solis

7206446997

asolis@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200788

Inspection Date: 09/20/2019

FIR Submit Date: 09/23/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455519

Location Name: Boomslang Fed 8-60 Number: 14B County: _____

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

FACILITY - API Number: 05-123-00 Facility ID: 455519

Facility Name: Boomslang Fed 8-60 Number: 14B

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

CORRECTIVE ACTIONS:

1 CA# 130942

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Rip rap spillway has been installed at inlet of sediment traps

COGCC Decision: _____

COGCC
Representative:

2 CA# 130943

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator
Comment: Armoring has been installed at inlet and outlet of culverts

COGCC Decision: _____

COGCC
Representative:

3 CA# 130944

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator
Comment: Tracking on slopes has been corrected

COGCC Decision: _____

COGCC
Representative:

4 CA# 130945

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator
Comment: Rip rap spillway has been installed at inlet of sediment traps. Wattle has been replaced if necessary.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 10/18/2019 4:13:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402214827	Culverts, sediment traps, etc

Total Attach: 1 Files