

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402214872

Date Received:  
10/18/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661  
Name of Operator: BISON OIL & GAS II LLC  
Address: 518 17TH STREET #1800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Abigail Wenk</u>	<u>7206446997</u>	<u>awenk@bisonog.com</u>
<u>Ariana Solis</u>	<u>7206446997</u>	<u>asolis@bisonog.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200790  
Inspection Date: 09/20/2019 FIR Submit Date: 09/23/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC Company Number: 10661  
Address: 518 17TH STREET #1800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454591

Location Name: Boomslang Fed 8-60 Number: 14A County: \_\_\_\_\_  
Qtrqr: NENE Sec: 14 Twp: 8N Range: 60W Meridian: 6  
Latitude: 40.666228 Longitude: -104.052089

FACILITY - API Number: 05-123-00 Facility ID: 454591

Facility Name: Boomslang Fed 8-60 Number: 14A  
Qtrqr: NENE Sec: 14 Twp: 8N Range: 60W Meridian: 6  
Latitude: 40.666228 Longitude: -104.052089

CORRECTIVE ACTIONS:

1 CA# 130946

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices. Date: 08/05/2019

Response: CA COMPLETED Date of Completion: 10/02/2019

Operator Comment: Ditches have been cleared of sediment, compacted, and wattles added as velocity checks.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 130947

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Rip rap spillway has been installed at inlet of sediment traps. Geotextile liner and rip rap has been added at outlets.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 130948

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Vehicle tracking pad installed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 130949

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Armoring installed at inlet and outlet of culverts.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**5** CA# 130950

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Tracking on slopes has been corrected.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 10/18/2019 5:04:25 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402214875	Corrective action photos
-----------	--------------------------

Total Attach: 1 Files