

**Government Hays 1**  
**API: 05-103-07109**  
**Inspection: 679705793**



**Photo 1. Location.**

Government Hays 1  
API: 05-103-07109  
Inspection: 679705793



Photo 2. Tank batteries.

Government Hays 1  
API: 05-103-07109  
Inspection: 679705793



**Photo 3. Water tank battery.**

Government Hays 1  
API: 05-103-07109  
Inspection: 679705793



Photo 4. Open top tank.

Government Hays 1  
API: 05-103-07109  
Inspection: 679705793



40.11939, -108.79048, 5380.2ft, 194°  
10/23/2019 11:39:26 AM

Photo 5. Chemical containers & separator.

**Government Hays 1**  
**API: 05-103-07109**  
**Inspection: 679705793**



**Photo 6. Water tank leak on north side.**



**Photo 7. Water tank leak on west side.**

**Government Hays 1**  
**API: 05-103-07109**  
**Inspection: 679705793**



**Photo 8. Berm height too short for crude oil tanks.**




**Photo 9. Berm low spot for open top tank.**

Government Hays 1  
API: 05-103-07109  
Inspection: 679705793



40.11964, -108.79066, 5389.6ft, 327°  
10/23/2019 11:54:17 AM

Photo 10. Berm height too short for water tanks.



40.11953, -108.7907, 5381.4ft, 4°  
10/23/2019 11:57:04 AM

Photo 11. Tank label.

Photo 10

Tank Battery  
Inspection: 679705385



Photo 9

Photo 8

Photo 12. Tank battery – Inadequate berms circled in yellow.