

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402225182

Date Received:
10/29/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
-		cogccinspections@srcenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500746

Inspection Date: 10/17/2019

FIR Submit Date: 10/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SRC ENERGY INC

Company Number: 10311

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 330604

Location Name: STATE BEATRICE-66N66W Number: 16SWNE County: _____

Qtrqtr: SWNE Sec: 16 Twp: 6N Range: 66W Meridian: 6

Latitude: 40.490113 Longitude: -104.780483

FACILITY - API Number: 05-123-00 Facility ID: 330604

Facility Name: STATE BEATRICE-66N66W Number: 16SWNE

Qtrqtr: SWNE Sec: 16 Twp: 6N Range: 66W Meridian: 6

Latitude: 40.490113 Longitude: -104.780483

CORRECTIVE ACTIONS:

1 CA# 131896

Corrective Action: Comply with Rule 1004. Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.

Date: 10/17/2019

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/29/2019

Operator Comment: After collaborating with the landowner on 10/28/19, he said he does not want SRC to do anything to the wellhead location or the production facility as there is good growth in both areas. Although there is a little bit of subsidence, he indicated the drainage is good and there are no ponding issues so there is no reason to try and fix the area. The landowner mentioned that SRC will do more harm than good. The recent disturbance at the

production facility is due to the harvesting of corn and they use the road between the alfalfa and corn for truck access in and out. The road is used for their agricultural purposes.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Attn: Chris Binschus

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Hilim

Signed: _____

Title: Administrative Assistant

Date: 10/29/2019 12:34:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files