

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401903279

Date Received:
01/13/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tim

Hart

thart@fremontpetroleum.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691401714

Inspection Date: 12/18/2018

FIR Submit Date: 12/21/2018

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 429883

Location Name: Pathfinder Number: C 14-01 1 County: _____

Qtrqr: SWS Sec: 1 Twp: 20S Range: 70W Meridian: 6
W

Latitude: 38.333375 Longitude: -105.179461

FACILITY - API Number: 05-043-

-00

Facility ID: 429883

Facility Name: Pathfinder Number: C 14-01 1

Qtrqr: SWS Sec: 1 Twp: 20S Range: 70W Meridian: 6
W

Latitude: 38.333375 Longitude: -105.179461

CORRECTIVE ACTIONS:

1 ☒ CA# 121428

Corrective Action: Comply with Rule 603.f .

Date: 01/21/2019

Response: CA COMPLETED

Date of Completion: 12/22/2018

Operator
Comment:

A fuel tank area was constructed, lined and bermed for fuel holding tanks during drilling. A tear in the liner resulted in 2 gals of fuel seeping into the ground. The torn liner was repaired immediately. However stained soil remained when the equipment was removed and later observed by inspector. Operator took action to remove the stained soil and replace with clean soil on Dec 22, 2018. See attached photo.

COGCC Decision: Approved via an AMI

COGCC
Representative:

2 ☒ CA# 121429

Corrective Action: Comply with Rule 603.f .

Date: 01/21/2019

Response: CA COMPLETED

Date of Completion: 12/22/2018

Operator Comment: A large tarp been rolled and left on location (for pick up at a later time) upon demobilization of drilg equipment. The inspector cited the debris upon his inspection on 12/18/18. Upon notification by the FIR, Operator immediately sent a crew to gather and dispose of the tarp. See attached photos.

COGCC Decision: Approved via an AMI

COGCC
Representative:

3 ☒ CA# 121430

Corrective Action: Construct a berm or diversion dike, site grading, or other comparable measures to comply with the Conditions Of Approval stated on form 2A DOC #400274234

Date: 01/03/2019

Response: CA COMPLETED

Date of Completion: 01/08/2019

Operator Comment: Site grading was completed and diversion measures were put in place along with SWM BMPS (straw wattles) during the week ending 1/08/19, See attached photos.

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: 1) 12/22/18: Removed fuel-stained soil and replaced with clean soil at area where fuel tanks had been located. See photos.
2) 12/22/18: Removed debris from location (large tarp that had been rolled up and set aside for removal, but still on location). See photos.
3) 1/02-1/08/19: Graded site, trenched perimeter of disturbed area and placed straw wattles for SWM BMPS. See photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tim Hart

Signed: _____

Title: President & CEO

Date: 1/13/2019 6:37:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401903279	FIR RESOLUTION SUBMITTED
401903284	Site grading of disturbed area
401903285	SWM BMPs - 2
401903286	SWM BMPS - 1
401903287	Fuel tank area
401903288	Post debris removal

Total Attach: 6 Files