

Pit Status Evaluation Form

Pit Overview:

Pit Name: PILAND	Facility ID: 113944
Current Status: Unknown	Status Date:
Current Operator: CHAMPLIN PETROLEUM COMPANY / 15550	
Updated Operator:	
Form 15 Pit Permit Doc #: 698629	Permit Date: 5/31/1983
Related Facilities: API # 05-001-07825 (Facility ID 202420)	

County: ADAMS			
Township: 2S	Range: 63W	Section: 31	QQ: NWNW
Original Latitude/ Longitude: 39.835763 / -104.484698			
Updated Latitude/ Longitude: 39.838043 / -104.487119			
Basis for Location Change:			
Lat/Long updated based on pit permit diagram and aerial imagery (circa 1993)			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 698629 | Date: 5/31/1983 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 500132454 | Date: 12/1/1995 |
| | Doc #: 200128267 | Date: 2/20/2008 |
| | Doc #: 671102272 | Date: 9/24/2014 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> | COGIS Document – Doc #: 347894 | Date: 7/7/1998 |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input checked="" type="checkbox"/> | Other: Pit plat - doc #698632 (5/31/1983) | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Pit backfilled prior to 12/1/1995 inspection.

Pit Status Review Summary:

Based on records review, the pit on location was backfilled prior to the 12/1/1995 field inspection and was replaced by a concrete vault. Pit status has been changed to Closed. Lat/long updated based on pit permit diagram and 1993 imagery.



