

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2019

Submitted Date:

10/27/2019

Document Number:

679705818**FIELD INSPECTION FORM**Loc ID 314291 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 200323Name of Operator: PICEANCE CREEK RANCH LTDAddress: 11539 CO RD 5City: RIFLE State: CO Zip: 81650**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Johnson, Dan	970-878-5103	piceance@dishmail.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228244	WELL	DM	08/18/1954	GW	103-05066	CLUBINE, ERIC 1	DM

**General Comment:**COGCC Inspection Report Summary.On 1-25-2019 at approximately 15:20, inspector Rick Moran, conducted a routine inspection at Piceance Cdreek Ranch well Eric Clubine 1 in Rio Blanco county.The following compliance issues were observed:

- 1) Well head sign missing "911" and nearest county road. Photo 4. Complete by 11-30-2019.
- 2) Submit a domestic tap flowline registration eForm 44. Complete by 11-30-2019.

Note: Domestic well located near edge of pasture.A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.This is a summary of inspection report 679705818.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Well head sign missing "911" and "CR 5".

Corrective Action: Install sign to comply with Rule 210.b. Date: 11/30/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Fencing around well ahead. Additional fencing lying on ground next to well head.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 1		
Comment:	The domestic tap registration must include the latitude and longitude of the flowline or wellhead connection for the domestic tap and the street address or the latitude and longitude of the point of delivery.		
Corrective Action:	Submit an eForm 44 Flowline Report per Rule 1101.b.	Date:	11/30/2019
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 228244	Type: WELL	API Number: 103-05066	Status: DM	Insp. Status: DM
Producing Well				
Comment:	No odor or sound detected of gas flowing. Well head pressure gage 465 psi. Unable to determine if the well was producing at the time of inspection.			
Corrective Action:			Date:	

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402222927	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973765">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973765</a>
679705819	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973763</a>