

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

679601838

FIELD INSPECTION FORM

Loc ID 310003 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		wellinspections@bayswater.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295503	WELL	SI	10/01/2018	OW	123-25733	LAMB 33-23	SI

General Comment:

(This area is currently blank for general comments.)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Appears to be stained soil at master valve of wellhead. See attached photo.		
Corrective Action:	Comply with Rule 605.d.		Date: 11/30/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift # 1			
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 295503 Type: WELL API Number: 123-25733 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday, November 4, 2019 at approximately 10:40, I, Inspector Brittani Santistevan, conducted an on-site inspection at LAMB 33-23 (Bayswater Exploration & Production), at location #: 310003 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. Appears to be stained soil at master valve of wellhead. Please remove and COMPLY WITH RULE 605.D. (Corrective Action Date: November 30, 2019) See attached photo #3, 4. FORM 10 DOC#: 402163455 (IN PROCESS) in COGCC DATA BASE.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	11/04/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601839	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980707