

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402211119

Date Received:

10/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 7950 JOHN T WHITE ROAD

City: FORT WORTH State: TX Zip: 76120

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Arthur, Denise

carla.white@omimexgroup.com

denise.arthur@state.co.us

Burn, Diana

diana.burn@state.co.us

Ash, Margaret

carlos.huertas@omimexgroup.com

margaret.ash@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200770

Inspection Date: 09/12/2019

FIR Submit Date: 09/13/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: OMIMEX PETROLEUM INC

Company Number: 66190

Address: 7950 JOHN T WHITE ROAD

City: FORT WORTH State: TX Zip: 76120

LOCATION - Location ID: 304893

Location Name: BLED SOE-63N43W Number: 30SE NW County: \_\_\_\_\_

Qtrqr: SE NW Sec: 30 Twp: 3N Range: 43W Meridian: 6

Latitude: 40.199740 Longitude: -102.218370

FACILITY - API Number: 05-125-00 Facility ID: 304893

Facility Name: BLED SOE-63N43W Number: 30SE NW

Qtrqr: SE NW Sec: 30 Twp: 3N Range: 43W Meridian: 6

Latitude: 40.199740 Longitude: -102.218370

CORRECTIVE ACTIONS:

1 ☒ CA# 130560

Corrective Action: Comply with 1002.f: Repair erosion degradation on access road and install or repair required BMPs for stabilization. Continue to monitor and manage location/disturbance in accordance with 1002.f rules, until location has passed final reclamation pursuant to Rule 1004

Date: 10/13/2019

Response: CA COMPLETED

Date of Completion: 10/15/2019

Operator  
Comment: Repaired erosion on access road. Photos are attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative: Photos provided show erosion concerns (head-cut) appear to remain at oil and gas access road. Corrective action does not appear to have been addressed in its entirety; A follow-up inspection will be conducted to determine compliance with 1002 rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Repaired erosion spot on access road.  
Pictures attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Carla White

Signed: \_\_\_\_\_

Title: Engineering Tech

Date: 10/16/2019 9:42:57 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402211119	FIR RESOLUTION SUBMITTED
402211150	6-30 repaired erosion
402211161	6-30 repaired erosion
402211167	6-30 repaired erosion

Total Attach: 4 Files