

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402213784

Date Received:
10/17/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Ariana Solis	720-644-6997	asolis@bisonog.com
Abigail Wenk	720-644-6997	awenk@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200786

Inspection Date: 09/20/2019 FIR Submit Date: 09/23/2019 FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452871

Location Name: Castor 8-59 Number: 19 County: _____

Qtrqtr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.644946 Longitude: -104.011983

FACILITY - API Number: 05-123-00 Facility ID: 452871

Facility Name: Castor 8-59 Number: 19

Qtrqtr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.644946 Longitude: -104.011983

CORRECTIVE ACTIONS:

1 CA# 130940

Corrective Action: Install/Repair Stormwater and erosion control BMPs in accordance with 1002.f. Ensure BMPs are installed in accordance with good engineering practice and maintained in proper functioning condition.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/07/2019

Operator Comment: Sediment traps have been repaired at the NE & NW corners with a riprap spillway & geotextile lining installed at the inlets.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 130941

Corrective Action: Install/Repair Stormwater and erosion control BMPs in accordance with 1002.f. Ensure BMPs are installed in accordance with good engineering practice and maintained in proper functioning condition.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/16/2019

Operator Comment: Bare areas on SE corner of pad have been hydromulched.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 10/17/2019 4:49:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402213784	FIR RESOLUTION SUBMITTED
402213810	SE Corner
402213813	Sediment Trap

Total Attach: 3 Files