

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402214872

Date Received:
10/18/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Abigail Wenk</u>	<u>7206446997</u>	<u>awenk@bisonog.com</u>
<u>Ariana Solis</u>	<u>7206446997</u>	<u>asolis@bisonog.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200790

Inspection Date: 09/20/2019

FIR Submit Date: 09/23/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454591

Location Name: Boomslang Fed 8-60 Number: 14A County: _____

Qtrqtr: NENE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.666228 Longitude: -104.052089

FACILITY - API Number: 05-123-00 Facility ID: 454591

Facility Name: Boomslang Fed 8-60 Number: 14A

Qtrqtr: NENE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.666228 Longitude: -104.052089

CORRECTIVE ACTIONS:

1 CA# 130946

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Ditches have been cleared of sediment, compacted, and wattles added as velocity checks.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 130947

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Rip rap spillway has been installed at inlet of sediment traps. Geotextile liner and rip rap has been added at outlets.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 130948

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Vehicle tracking pad installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 CA# 130949

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Armoring installed at inlet and outlet of culverts.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

5 CA# 130950

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 10/02/2019

Operator Comment: Tracking on slopes has been corrected.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 10/18/2019 5:04:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402214872	FIR RESOLUTION SUBMITTED
402214875	Corrective action photos

Total Attach: 2 Files