

RECEIVED

DEC 02 1980

11-25-80

COLO. OIL & GAS CONS. COMM.



The Application(s) for Permit to Drill (OGCC Form 2) enclosed herewith cannot be processed at this time for the reason(s) stated below:

29-1 Vern Harley SW NW 29-9N-52W

- ☐ No plugging bond
- ☐ No surface bond ☐ Bond not signed
- ☐ No filing fee (\$75) ☐ Filing fee check not signed
- ☐ Application for Permit to Drill (OGCC Form 2) not signed
- ☐ Letter of waiver from owners of offsetting lease(s)
- ☒ Location not in accordance with Rule 318 or Spacing Order(s) *Less than 600 ft. from Lease Line*
- ☐ Location not clearly reported
- ☒ Incomplete item(s) number(s) *#15* on Application to Drill (OGCC Form 2)
- ☐ Name of proposed objective horizon or geological formation
- ☐ Other

Please correct and resubmit.

OIL & GAS CONSERVATION COMMISSION

✓ We inadvertently overlooked the 1/2 mi/29 in the original application. ROMAC owns all leases within one mile of the drill site.

R C Becker