

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/14/2019

Document Number:

695101749**FIELD INSPECTION FORM**Loc ID 308685 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278888	WELL	TA	11/15/2018	GW	071-08451	DEMPSEY 31-22	TA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

DEBRIS

Comment:

PHOTO 3: THERE IS A LARGE PILE OF WHAT APPEARS TO BE LOGGING  
OPERATION DEBRIS BEING STORED ON LOCATION.

Corrective Action:

REMOVE BEBRIS FROM LOCATION PER FULE 603.f.

Date: 02/14/2020

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment:

IS PLUMBED TO SURFACE

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 278888 Type: WELL API Number: 071-08451 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: "Well was found in state of Temporary Abandonment.

Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 12/14/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101750	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989475">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989475</a>