

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402246469

Date Received:
11/21/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tom Beardslee

tom.beardslee@state.co.us

Distribution, Evergreen

cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695100164

Inspection Date: 02/11/2019

FIR Submit Date: 02/11/2019

FIR Status: _____

Inspected Operator Information:

Company Name: PIONEER NATURAL RESOURCES USA INC

Company Number: 10084

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING State: TX Zip: 75039

LOCATION - Location ID: 308507

Location Name: LORENCITO-634S66W Number: 7NWNE County: LAS ANIMAS

Qtrqr: NWNE Sec: 7 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.104620 Longitude: -104.819230

FACILITY - API Number: 05-071- -00 Facility ID: 273107

Facility Name: LORENCITO Number: 2-7-34-66

Qtrqr: NWNE Sec: 7 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.104620 Longitude: -104.819230

CORRECTIVE ACTIONS:

1 CA# 122430

Corrective Action: Comply with Rule 603.f .

Date: 03/11/2019

Response: CA COMPLETED

Date of Completion: 02/25/2019

Operator
Comment:

Complied with Rule 603.f

COGCC Decision: _____

COGCC
Representative:

2 CA# 122431

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 03/11/2019

Response: CA COMPLETED

Date of Completion: 02/25/2019

Operator
Comment: Disposed of Non-E&P Waste

COGCC Decision: _____

COGCC
Representative:

3 CA# 122432

Corrective Action: MOVE FREEBOARD MARKER TO THE LOWEST BANK OF PIT. Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 02/12/2019

Response: CA COMPLETED

Date of Completion: 08/12/2019

Operator
Comment: Moved freeboard marker to the lowest bank

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: No photos of the CA are available currently

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed: _____

Title: Regulatory Specialist

Date: 11/21/2019 4:39:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files