

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402242810

Date Received:

11/20/2019

Spill report taken by:

Kosola, Jason

Spill/Release Point ID:

469265

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>EVERGREEN NATURAL RESOURCES LLC</u>	Operator No: <u>10705</u>	Phone Numbers
Address: <u>1801 BROADWAY SUITE 350</u>		Phone: <u>(719) 846-7898</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Cheri Morgan</u>		Mobile: <u>()</u>
		Email: <u>cheri.morgan@enrllc.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402241276

Initial Report Date: 11/17/2019 Date of Discovery: 11/13/2019 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NESW SEC 21 TWP 32S RNG 67W MERIDIAN 6Latitude: 37.240970 Longitude: -104.894320Municipality (if within municipal boundaries): _____ County: LAS ANIMAS

Reference Location:

Facility Type: OTHER☒ Facility/Location ID No 259341Spill/Release Point Name: Bladerunner☐ No Existing Facility or Location ID No.Number: 23-21☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=100Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Cool Sunny & BreezySurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Temporary tanks were set in a staging area near the Bladerunner location for a job to be performed in the area and were attached to a gathering line to fill. Evergreen employee came to location and noticed the valve had not been shut properly causing the tank to overflow. It is estimated 120 bbls of produced water was released into the field ran down through a culvert and across and lease road. The employee isolated the valve immediately. No State Waters were involved and the landowner was notified. Root cause investigation is ongoing & further repairs are in progress.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
11/13/2019	COGCC	Jason Kosola	-	Email
11/13/2019	LACOG	Robert Lucero	-	Email
11/13/2019	Landowner	Warren McDonald	-	Phone Call

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 11/19/2019		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	120	3	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 873 Width of Impact (feet): 66

Depth of Impact (feet BGS): _____ Depth of Impact (inches BGS): _____

How was extent determined?

Visual inspection and GIS mapping

Soil/Geology Description:

From the NRCS Soil Survey Map: Trujillo sandy loam

Depth to Groundwater (feet BGS) 50 Number Water Wells within 1/2 mile radius: 7

If less than 1 mile, distance in feet to nearest Water Well 1085 None ☐ Surface Water 690 None ☐

Wetlands 0 None ☐Springs 172 None ☐Livestock 0 None ☐Occupied Building 870 None ☐

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS#1 Supplemental Report Date: 11/19/2019Cause of Spill (Check all that apply) ☒ Human Error ☐ Equipment Failure ☐ Historical-Unknown
☐ Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

Lease operator covering area was helping with the filling of tanks. Lease operator was new to this type of job, and was instructed to close the valve to stop the water from filling the tank. Lease operator did not confirm with manager on site and closed the wrong valve causing the tank to overflow.

Describe measures taken to prevent the problem(s) from reoccurring:

Proper standard operating procedures needs to be written and put in place for all individuals when working with staging areas and filling tanks. Supervisor on site will make sure clear and concise instruction and communication is used.

Volume of Soil Excavated (cubic yards): 0Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment
☐ Other (specify) _____Volume of Impacted Ground Water Removed (bbls): 0Volume of Impacted Surface Water Removed (bbls): 0**REQUEST FOR CLOSURE**

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Water quality from three corresponding wells to which the produced water was used to fill the tank is attached for reference. Evergreen and its consulting geochemical specialists have found, after 20 years operating in the Raton Basin CBM field, that soil sampling no longer adds useful data on smaller, short-term spills as land uses and the environment are not sensitive to short-term exposure to CBM produced water. Effects to soil chemistry from short-term CBM produced water spills are temporary and shallow for several reasons: the water does not contain crude oil or liquid hydrocarbons; the TDS is significantly less than 10,000 mg/L; it is suitable for livestock watering, wildlife and in many cases surface discharge. Mixed with other water it is suitable for irrigation without impact.

When requested by the agency or landowner Evergreen will collect new soil samples.
Evergreen Natural Resources request closure of this spill based on this statement and attached water quality data.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Cheri MorganTitle: Regulatory Specialist Date: 11/20/2019 Email: cheri.morgan@enrllc.com

COA Type

Description

	Based on review of information presented and COGCC spill inspection it appears that no further action is necessary at this time. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water or vegetation is found to be significantly impacted, further investigation and/or remediation activities may be required at the site.
--	--

Attachment Check List

Att Doc Num

Name

402242810	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402243124	ANALYTICAL RESULTS
402243125	ANALYTICAL RESULTS
402244465	ANALYTICAL RESULTS
402247601	FORM 19 SUBMITTED

Total Attach: 5 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)