

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: AREA OF IMPACTED SOIL BETWEEN PUMPJACK AND SOUND WALL.
PHOTO 4: AREA OF IMPACTED SOIL AROUND WELLHEAD.

Corrective Action:

Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907.

Date: 12/20/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead

1

Comment:

IS PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

TELEMETRY EQUIPMENT

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 284892 Type: WELL API Number: 071-08804 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402245313	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994113
695101779	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994110