



02496698

OGCC FORM 4
Rev 8/89

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

<input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input type="checkbox"/> OTHER		3 FEDERAL INDIAN OR STATE LEASE NO <i>Free</i>
2 NAME OF OPERATOR <i>Joe Doyle</i>		6 PERMIT NO
3 ADDRESS OF OPERATOR		7 API NO
CITY	STATE	8 WELL NAME <i>#1 South Coalmont</i>
ZIP CODE		9 WELL NUMBER <i>#1</i>
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>3925' FNL 1730' FWL</i> At proposed prod zone <i>Sec 6, T6N, R80W</i>		10 FIELD OR WILDCAT <i>Wildcat</i>
12 COUNTY <i>Jackson</i>		11 QTR. QTR. SEC., T.R. AND MERIDIAN <i>Sec. 6, T6N, R80W</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER _____

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
 - ABANDONED LOCATION (WELL NEVER DRILLED. SITE MUST BE RESTORED WITHIN 6 MONTHS)
 - REPAIRED WELL
 - OTHER
- *Use Form 3 - Well Completion or Recompletion Report and Log for subsequent report of Multiple Commingled Completions and Recompletions

13C. NOTIFICATION OF:

- SHUT-IN TEMPORARILY ABANDONED (DATE _____ (REQUIRED EVERY 6 MONTHS))
- PRODUCTION RESUMED (DATE _____)
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK *Proposed for Nov. 97*

1. Set CIBP 50' above Shannon perf 5074'-5084' w/2 sk cement on top CIBP.
2. Perf 5 1/2" casing at 680' & squeeze 100' plug in & out of 5 1/2" & across 7 5/8" casing shoe at 630'.
3. Spot 30' plug at surface in & out of 5 1/2" casing.
4. Cut head off 4' below GL & weld on plate w/well info.

16. I hereby certify that the foregoing is true and correct

SIGNED *William J. Rippy Jr.*

TELEPHONE NO. *970-858-3736*

NAME (PRINT) *BILL RIPPY*

TITLE *Contractor (Agent)*

DATE *11/10/97*

(This space for Federal or State office use)

APPROVED _____

CONDITIONS OF APPROVAL, IF ANY: _____

TITLE _____

DATE _____

COLORADO OIL AND GAS CONSERVATION COMMISSION
NORTHWEST AREA OFFICE
FAX COVER SHEET
(970) 858-7521

November 10, 1997

TO: MORRIS BELL

FROM: BILL RIPPY

PAGES TO FOLLOW: 1

Morris,

Here is the plugging procedure for Joe Doyle.

Thanks!

Jaime