

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402252729

Date Received:  
12/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

|                             |                     |                             |
|-----------------------------|---------------------|-----------------------------|
| Contact Name                | Phone               | Email                       |
| <u>Victoria Dizghinjili</u> | <u>303-825-4822</u> | <u>vdizghinjili@kpk.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 688402011  
Inspection Date: 04/24/2019 FIR Submit Date: 04/24/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320506

Location Name: IVEY-61S68W Number: 11SESE County: ADAMS  
Qtrqr: SESE Sec: 11 Twp: 1S Range: 68W Meridian: 6  
Latitude: 39.973661 Longitude: -104.964653

FACILITY - API Number: 05-001-00 Facility ID: 271836

Facility Name: IVEY Number: 16-11  
Qtrqr: SESE Sec: 11 Twp: 1S Range: 68W Meridian: 6  
Latitude: 39.973661 Longitude: -104.964653

CORRECTIVE ACTIONS:

1 CA# 124575

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED Date of Completion: 11/28/2019

Operator Comment: Equipment has been anchored down. Berms have been repaired and raised. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 124576

Corrective Action: Paint tanks per Rule 804.

Date: 07/24/2019

Response: CA COMPLETED

Date of Completion: 11/28/2019

Operator Comment: KPK plans to repaire/paint tanks during a summer time (2020).

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 124577

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 11/28/2019

Operator Comment: Berms have been repaired and raised. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Steve Hamilton

Signed: \_\_\_\_\_

Title: Field Supervisor

Date: 12/3/2019 3:15:17 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <b>Document Number</b> | <b>Description</b> |
|------------------------|--------------------|
| 402252759              | CA completed PIC1  |
| 402252765              | CA completed PIC2  |
| 402252767              | CA completed PIC3  |
| 402252772              | CA completed PIC4  |

Total Attach: 4 Files