

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2019

Submitted Date:

12/12/2019

Document Number:

688306469

FIELD INSPECTION FORM

Loc ID 320684 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10695
Name of Operator: BEHRENS RESOURCES INC
Address: PO BOX 188
City: DEER TRAIL State: CO Zip: 80135

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Behrens, Vic	(303) 810-6382	behrens@netecin.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204460	WELL	SI	09/01/2018	OW	005-06545	Schmidt 3	SI

General Comment:

[Annual Bradenhead Test Inspection](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

	Type	#			corrective date
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:					
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked		# 4			
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 204460 Type: WELL API Number: 005-06545 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI since Jul 2017. MIT needed within 30 days. Update Form 7's.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 01/13/2020

BradenHead

Comment: Bradenhead 0 psi, Casing 5 psi, Tubing 0 psi. Operator to submit Form 17.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306508	Behrens Resources Schmidt 3 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011737
688306509	Behrens Resources Schmidt 3 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011738