

HILL RANCH 07-02V API# 05-071-07199 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 13, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901570



PHOTO 1: THE PACKINGS WERE CHANGED AND GREASED TO PREVENT THE WATER FROM LEAKING. THE WING NUT WAS SECURLY FASTENED TO ENSURE GOOD MECHANICAL CONDITION.

HILL RANCH 07-02V API# 05-071-07199 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 13, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901570



PHOTO 2: THE WATER WAS PULLED BY A VACUUM TRUCK AND SPILL WAS CLEANED UP