



1120 Lincoln Street, STE 801
Denver, CO 80203

December 23, 2019

Joseph Forma
O'Brien Energy Resources Corp
18 Congress St, Ste 207
Portsmouth, NH 03801

Dear Mr. Forma,

O'Brien Energy is receiving this letter because, based on COGCC records, the COGCC has reason to believe that in addition to the well on the Warning Letter the wells listed below present one or more compliance issues as well. The wells provided below must be compliant by the Corrective Action date provided on the Warning Letter.

Please do not hesitate to contact me with any questions regarding these compliance issues, or if these wells were incorrectly identified.

- | | | | |
|--------------|-------------------------|--------------|--------------------|
| 1. 123-19776 | LOST CREEK 1 | 6. 123-21976 | SOUTH LOST CREEK 8 |
| 2. 123-19863 | LOST CREEK O'BRIEN 2-20 | 7. 123-23984 | LOST CREEK 31 |
| 3. 123-20424 | LOST CREEK O'BRIEN 3-20 | 8. 123-23985 | LOST CREEK 36 |
| 4. 123-20458 | LOST CREEK O'BRIEN 4-20 | 9. 123-23992 | LOST CREEK 35 |
| 5. 123-21237 | NORTH LOST CREEK 11 | | |

Sincerely,

Deborah Abrams
Engineering Technician



P 303.894.2100 x5158 | F 303.894.2109
1120 Lincoln Street, Suite 801, Denver, CO 80203
deborah.abrams@state.co.us | www.colorado.gov/cogcc

