

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402115159

Date Received:

07/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dustin Stransky</u>	<u>(303) 294-7805</u>	<u>dstransky@hpres.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696300323
Inspection Date: 07/11/2019 FIR Submit Date: 07/12/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 420723

Location Name: Lion Creek Number: 06-23H County: WELD
Qtrqtr: SESE Sec: 23 Twp: 11N Range: 64W Meridian: 6
Latitude: 40.900128 Longitude: -104.504992

FACILITY - API Number: 05-123-00 Facility ID: 420727

Facility Name: Lion Creek Number: 06-23H
Qtrqtr: SESE Sec: 23 Twp: 11N Range: 64W Meridian: 6
Latitude: 40.900128 Longitude: -104.504992

CORRECTIVE ACTIONS:

1 CA# 126990

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Date: 08/12/2019

Response: CA COMPLETED Date of Completion: 07/17/2019

Operator Comment: Bird Protector has been installed on the glycol unit. In addition, all valves, pipes, and fittings have been securely fastened to ensure good mechanical conditions and properly maintained per Rule 605.d.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

2 CA# 126991

Corrective Action: For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."

Date: 08/12/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: Stained soil at northwest back bottom valve has been properly treated and disposed of in accordance with Rule 907.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

3 CA# 126992

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/12/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: Loadline bucket lids have been installed. In addition, all valves, pipes, and fittings have been securely fastened to ensure good mechanical conditions and properly maintained per Rule 605.d.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

4 CA# 126993

Corrective Action: For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."

Date: 08/12/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: Stained soil at well has been properly treated and disposed of in accordance with Rule 907.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed: _____

Title: Regulatory Compliance

Date: 7/19/2019 9:37:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402115159	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files