

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2020

Submitted Date:

01/08/2020

Document Number:

695101985**FIELD INSPECTION FORM**Loc ID 322219 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74975Name of Operator: SAN MARCO PETROLEUM INCAddress: 240 MILWAUKEE ST STE 200City: DENVER State: CO Zip: 80206-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Marco, San		sanmarcopetr@cs.com	
Sheridan, John	303-321-0100	sanmarcopetr@cs.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209942	WELL	PR	01/01/2017	OW	043-06020	ADAMIC 1-20	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	PHOTO 2: WELL SIGN, CONTACT PHONE NUMBER SIZE IS INADEQUATE AND 911 IS NOT POST ON SIGHT.		
Corrective Action:	INSTALL SIGN THAT COMPLIES WITH RULE 210.d. 24 HOURS TO POST EMERGENCY CONTACT NUMBER.	Date:	01/09/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: IT APPEARS THAT WELLHEAD IS LEAKING PRODUCED OIL, AREA OF IMPACTED SOIL APP. 6' BY 3' AROUND WELLHEAD. PHOTO 5: VALVE ON 210 BBL TANK IS SEEPING. THERE IS AN AREA OF IMPACTED SOIL APP. 3' BY 1' NEAR SEEPING VALVE. PHOTO 6: LOADOUT LINE IS PLUMBED OUTSIDE SECONDARY BMP. THERE IS AN AREA OF IMPACTED SOIL OUTSIDE OF BURM) APP1' BY 2' AROUND LOADOUT.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.	Date:	02/08/2020
Type	OTHER		
Comment:	PHOTO 4: A BULLPLUG ON 210 BBL TANK IS LEAKING. THERE IS AN AREA OF IMPACTED SOIL APP. 3' BY 6' NEAR LEAKING PLUG. CALLED CONTACT NUMBER POSTED ON BATTERY SIGN AND HAD TO LEAVE A MESSAGE.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e." 24 HOURS TO REPAIR LEAKING BULLPLUG 30 DAYS FOR SOIL. CA DATE 1-9-20.	Date:	01/09/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	#		
Comment:	PHOTO 7: APPEARS THAT GEAR BOX ON PUMPJAKE IS LEAKING, THERE IS AN AREA OF IMPACTED SOIL BENEATH GEARBOX.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.f.	Date:	02/08/2020

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 209942	Type: WELL	API Number: 043-06020	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		<div>PHOTO 6: LOADOUT LINE IS PLUMBED OUTSIDE SECONDARY BMP. THERE IS AN AREA OF IMPACTED SOIL OUTSIDE OF BURM) APP. 1' BY 2' AROUND LOADOUT.</div>				
Corrective Action:		<div>INSTALL SECONDARY BMP TO PREENT OILY WASTE FROM MIXING WITH STORM WATER PER RULE 1002.f.</div>				Date: 02/08/2020
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101986	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031105