



FORM
6
Rev
05/18

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:
402280211

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 5

Contact Name: Mike Hickey

Name of Operator: COLORADO OIL & GAS CONSERVATION

Phone: (303) 8942100

Address: 1120 LINCOLN ST SUITE 801

Fax:

City: DENVER State: CO Zip: 80203

Email: michael.hickey@state.co.us

For "Intent" 24 hour notice required, Name: Tel:

COGCC contact: Email:

API Number 05-001-08443-00

Well Name: R C NAUMAN (OWP) Well Number: 4

Location: QtrQtr: SENW Section: 14 Township: 1S Range: 67W Meridian: 6

County: ADAMS Federal, Indian or State Lease Number:

Field Name: SPINDLE Field Number: 77900

☐ Notice of Intent to Abandon

☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.966510 Longitude: -104.858220

GPS Data:

Date of Measurement: 02/11/2013 PDOP Reading: 1.4 GPS Instrument Operator's Name: CRAIG BURKE

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems

☐ Other

Casing to be pulled: ☐ Yes ☐ No Estimated Depth:

Fish in Hole: ☐ Yes ☐ No If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
SUSSEX	5014	5030	09/01/2017	B PLUG CEMENT TOP	4950

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	221	180	221	0	VISU
1ST	7+7/8	4+1/2	10.5	5,143	150	5,143	4,543	CALC
	7+7/8	4+1/2	Stage Tool	1,085	150	1,085	425	CALC

Date Run: 1/13/2020 Doc [#402280211] Well Name: R C NAUMAN (OWP) 4

Page 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4950 with 2 sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 1190 ft. with 50 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 360 ft. with 150 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: 09/01/2017
of _____

*Wireline Contractor: Excell Services

*Cementing Contractor: Excell Services

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☒ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Well plugged by OWP:

Missing Documents:

Cement tickets

Wireline tickets

Wellsite operations report

Plugging Procedure

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Aaron Katz

Title: Northwest Area Engineer Date: 1/8/2020 Email: aaron.katz@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402280256	WELLBORE DIAGRAM
402280257	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)