

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2020

Submitted Date:

01/10/2020

Document Number:

694400274

FIELD INSPECTION FORMLoc ID 465709 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nelson, Justin		Justin_Nelson@Oxy.com	
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465709	LOCATION	AC			-	JODSTER SOUTH 24-25HZ PAD	AC

General Comment:

Inspected Facilities

Facility ID: 465709 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: This inspection is subsequent to document #694400263.
 The previous inspection documented low frequency noise levels measured at 75.9 DBC average.
 A follow up measurement of low frequency levels was performed on 1/2/2020 from 15:26 and ran continuously through 1/3/2020 at 14:16. Measurements were taken from 40.377553, -104.950917.
 The sound study shows an overall DBC average of 70.4. However, due to the proximity of the metering location and the drilling unit to HWY-402, and active gravel mining operations, "nighttime" data is isolated (7am to 7pm). The resulting DBC average from 19:00 to 7:00 is 70.8.
 A corrective action is assigned to the location, citing rule 802.d.

 Rule 802.d. In situations where the complaint or Commission onsite inspection indicates that low frequency noise is a component of the problem, the Commission shall obtain a sound level measurement twenty-five (25) feet from the exterior wall of the residence or occupied structure nearest to the noise source, using a noise meter calibrated to the db (C) scale. If this reading exceeds 65 db(C), the Commission shall require the operator to obtain a low frequency noise impact analysis by a qualified sound expert, including identification of any reasonable control measures available to mitigate such low frequency noise impact. Such study shall be provided to the Commission for consideration and possible action.
 See attachments for weather, and sound audit details.

END OF REPORT.

Corrective Action: **Comply with Rule 802. For low frequency issues, obtain a low frequency impact analysis and identify control measures.**

Date: 01/13/2020

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: _____

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402282099	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033693
694400275	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033685
694400276	Weather Data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033686