

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402285062

Date Received:

01/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696501286

Inspection Date: 12/12/2019

FIR Submit Date: 12/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 305242

Location Name: BERNHARDT-64N66W Number: 7SESW County: _____

Qtrqr: SESW Sec: 7 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.319596 Longitude: -104.823246

FACILITY - API Number: 05-123- -00 Facility ID: 448358

Facility Name: BERNHARDT 7-16 BATTERY Number: _____

Qtrqr: SESW Sec: 7 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.319596 Longitude: -104.823246

CORRECTIVE ACTIONS:

1 CA# 135280

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: Berms have been repaired. Please see attached pictures.

COGCC Decision: _____

COGCC
Representative:

2 CA# 135281

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: Mechanical issues have been fixed, valves have been tightened. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

3 CA# 135282

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: Stained soil around tank, on berms have been removed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 1/17/2020 3:49:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402289418	Stained soil removed PIC1
402289419	Stained soil removed PIC2
402289420	Stained soil removed PIC3
402289421	Repaired berms PIC4
402289422	Repaired berms PIC5

Total Attach: 5 Files